

JONES MASONRY/GREG JONES

P.O. Box 24893, San Jose, CA 95154

(408) 377-7512 • Lic. # 390359 • Fax (408) 879-0379

S_Jones@pacbell.net

Report & Estimate

Customer Name Lisa Gilmore Date: 6/15/11

Address 678 San Miguel Ave City Santa Clara State Ca Zip _____

Phone: 246-5020 Fax: _____ Cell: _____

Chimney is 1 ft short of code may have passed inspection by City at this height

Firebox has been cut through when room was added to have a see through type of fireplace see other

Exterior Shell OK \$ _____

Throat OK \$ _____

Damper OK \$ _____

Facing OK \$ _____

Spark Arrestor exists \$ _____


Other See through fireplaces have a tendency to smoke and not draw the best so elevation of burn grate helps and dry firewood and position of grate all can help draw

there are some smoke stains above opening - on stone

Total Estimate \$ _____

Not responsible for draw of fireplace

We do not verify attic space. If not enough room, some of the roof may be needed to be removed by others and replaced. We do not do this work.



Fee \$125.00 on Site - 1 Story - 1 Chimney. 125.00

Add \$25.00 Per Fireplace, or 2 Stories. _____

Out of Area Charges May Change. _____

Total Fees 125.00

(If not paid on site, report will not be generated.)

paid check # 1080